HARPER COUNTY ROAD & BRIDGE

Weekly County Commission Report

January 11-15, 2016

KENT STONEBRAKER-EAST FOREMAN

- 1. Trucks 217, 305, 310 & 606 hauling sand to Rd's 749-M, 749-N & 682-18. Dozer 627 pushing up sand at the Oliver Pit. Graders patrolling.
- 2. Trucks 217, 305 & 606 hauling sand to Rd's 759-Q & 761-P. Dozer 627 pushing up sand at the Oliver Pit. Graders patrolling.
- 3. Excavator 635 burning tree pile in ditch along Rd 674-15. Dozer 627 pushing up sand at the Oliver Pit. Trucks 216, 310 & 606 hauling sand to Rd's 761-O & P & 700-29. Graders patrolling.
- 4. Excavator 635 fixing field entrance on Rd 676-13. Excavator burning tree pile in ditch along Rd 674-15. Trucks 216 & 217 hauling shale to field entrance on Rd 676-13. Truck 305 hauling shale to field entrance on Rd 763-J. Trucks 217, 305 & 606 hauling shale to Rd 700-29. Dozer 627 pushing sand at the Oliver Pit. Graders patrolling.
- 5. Dozer 627 pushing up sand at the Oliver Pit. Graders patrolling. Trucks 310, 217 & 606 hauling sand to Rd's 700-29, 755-U, 686-27 & 767-V.

JIM THOMPSON-SHOP FOREMAN

- 1. DOA 2015 Ford, service job-25,120 miles.
- 2. Repairs/maintenance to #310 2006 Sterling Truck & #605 2006 Freightliner.
- 3. Clean & organize shop.
- 4. #632 CAT 320, service call-replaced fuel filter. #500 2012 Chevrolet Pickup, replaced rear shocks. #305 2015 International, PTO not working-found loose fuse.
- 5. #627 Cat Dozer, service call-hydraulic leak. #305 2015 International, service job-15,075 miles.

LAWRENCE SMITH-WEST FOREMAN

Cleaned sand out of ditches on Rd 721-Y & hauled to Rd's 708-11 & 12 & 729-Y to cover muddy spots. Sanded Rd's 731-M. N. O & P & 684-12. Excavator 632 helping Bridge Crew at Bridge 713-D. Graders patrolling & spreading sand. Changed blades on Graders & fixed flat tires on Trucks.

JEFF NULIK-BRIDGE FOREMAN

- 1. Installed stringer plates at Bridge 713-D.
- 2. Continued installing stringer plates at Bridge 713-D.
- 3. Completed stringer plates at Bridge 713-D. To Anderson Welding to order welding leads.
- 4. Installed 2 piling stubs at Bridge 713-D. Patched hole in steel deck at Bridge 676-13.
- 5. Loaded & hauled scrap iron to Kelly Salvage.